REMEDIAL ACTION CERTIFICATION FORM

1.	. Site Name and Location:						
	Site 40 is located on the South side of Van Buren Boulevard one quarter of a mile west of Highway 215, March Air Force						
	Base Riverside County, Moreno Valley, CA 92518-2349						
	A. List an other names that have been used to identify sites: Alessandro Aviation Field.						
	B. Address of site if different from above:						
	C. Assessor's Parcel Numbers:						
2.	Responsible Parties:						
	Name: March Air Force Base Name: Air Mobility Command						
	Title: Base Conversion Agency Title: Department of U.S.A.F						
	Firm: Department of Defense Firm: HQ AMC/CEVE						
	Address: Riverside Address: 507 A Street						
	Scott AFB, Illinois						
	City:Moreno Valley City:						
	Zip: 92518-2349 Zip: 62225-5022						
	Telephone: (909) 655-4858 Telephone: ()						
	Relationship to site: such as generator, hauler, etc.						
	Current Landowner/Operator: Landowner and Operator						
3.	Brief Description and History of the Site: Site 40 is a former landfill used for depositing wastes from March AFB. It is approximately 18 acres of rolling land and the central portion of the property consists of a pond which accumulates surface runoff. Buried						

drums at this landfill were filled with sodium hydroxide, roofing tar, asphalt solids and waste, and oil and grease. The primary objective of the Removal Action was to prevent potential contamination of the surface and storm water in the channel due to exposure to drums and debris buried in the channel bed. Field execution of the removal action resulted in removing approximately 70 5-gallon to 20-gallon decomposed drums filled with sodium hydroxide and 30 55-gallon drums filled with oil and grease solids. Approximately 200 cubic yards of contaminated overburden material extending above and to the sides of the drums, in addition to the drums, were combined in 85-gallon overpack drums and transported off-site for disposal. Approximately 14 tons of debris containing non-friable asbestos at less than 10% by total weight were placed in a lined roll-off box and transported to BDC Services, Inc. for disposal. As part of Site 40 restoration, the water's elevation in the pond was raised by installing a concrete weir at the outlet of the pond. Each site location, including the creek bed, was restored. Vegetation destroyed during construction was replaced with California native plants. Site 40 has been clean closed. Conformational sampling of the drum excavation areas was performed and the levels were non detect and/or below the regulatory limits.

4	Type	of	Site:
---	------	----	-------

	Included in the Site Mitigation Work Plan?
	Yes X No
	RCRA-Permitted Facility Bond - funded
	RCRA Facility Closure RP - funded
	*NPL X
	Federal Facility X
	Other (i.e., walk-in): Explain Briefly:
5.	Size of Site:
	Small Medium Large Extra Large _X
C	Datas of Damadial Jaking
υ.	Dates of Remedial Action:
	a. Initiated 27 July, 1994 b. Completed 28 June, 1995

^{*}Per SARA, any NPL site that is not permanently cleaned must be scheduled for a follow-up visit after 5 years to verify that cleanup measures are still satisfactory.

	Initial Removal or Remedial Action (site
v	inspection/sampling) Final Remedial Action
X	RCRA enforcement/closure action
	No action, further investigation verified that no
	cleanup action at site was needed.
Α.	Type of Remedial Action : Excavation and off-site disposal of approximately 70 5-gallon to 20 -gallon
	disposal of approximately /0 5-gallon to 20-gallon drums filled with sodium bydrovide and 30 55-gallon
	drums filled with sodium hydroxide and 30 55-gallon drums filled with roofing, asphalt solids and waste,
	and oil and grease. 200 cubic yards of contaminated
	overburden soil in addition to 14 tons of debris
	containing non-friable asbestos were transported off-
	site for disposal. Approximately 6,800 cubic yards o non hazardous materials (consisting of soil and debri
	were transported to IRP Site 6a for disposal in the
	lined waste cell.
В.,	Estimated quantity of waste associated with the site
	(i.e., tons/gallons/cubic yards) which was:
1	
2.	untreated (capped sites) Amount:
	X removed Amount: 100 drums, 200 cub ds of contaminated soil, 14 tons of non-friable asbesto
y CLIL	
deb.	ris, and 6.800 cubic vards of non hazardous materials.
deb.	ris, and 6,800 cubic yards of non hazardous materials.
deb:	ris, and 6,800 cubic yards of non hazardous materials. anup Levels/Standards:
deb:	ris, and 6,800 cubic yards of non hazardous materials. anup Levels/Standards:
deb:	ris, and 6,800 cubic yards of non hazardous materials. anup Levels/Standards: What were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or
deb:	what were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or workplan:
deb:	ris, and 6,800 cubic yards of non hazardous materials. anup Levels/Standards: What were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or workplan: Cleanup standards were set for residential or
deb:	what were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or workplan: Cleanup standards were set for residential or unrestricted use .
deb:	ris, and 6,800 cubic yards of non hazardous materials. anup Levels/Standards: What were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or workplan: Cleanup standards were set for residential or
Clea	what were the cleanup standards established by DTSC pursuant to the final remedial action plan (RAP) or workplan: Cleanup standards were set for residential or unrestricted use .

9. DTSC Involvement in the Remedial Action:

A. Did the Department order the Remedial Action?

	Yes No _X _ Date of Order
В.	Did the Department review and approve (check appropriate action and indicate date of review/approval if done):
X	Sampling Analysis Procedures Date October 13, 1994
X	Health & Safety Protections Date October 13, 1994
X	Removal/Disposal Procedures Date October 13, 1994
X	Removal Action Plan Date January 18, 1995
С	If site was abated by a responsible party, did the Department receive a signed statement from a licensed professional on all Remedial Action? Yes X No Dates (from) 7/94 (to) 2/95
D.	Did a registered engineer or geologist verify that acceptable engineering practices were implemented? Yes X No Name Scott Morris, P.E. Date of verification February 10, 1995
王	Did the Department confirm completion of all Remedial Action? Yes X No Date of verification June 28, 1995 (i.e. manifest, sampling, demonstrated installation and operation of treatment)
F.	Did the Department (directly or through a contractor) actually perform the Remedial Action? Yes NoX Name of contractor
G"	Was there a community relations plan in place? Yes X No
Н.	Was a remedial action plan developed for this site? Yes No X An Action Memorandum dated September 1994, was prepared for the rapid response remediation of Site 40.
Ι.,	Did DTSC hold a public meeting regarding the draft RAP? Yes No X The Air force held a public meeting on October 19, 1994.
J.	Were public comments addressed? Yes X No Date of DTSC analysis and response: October 19,1994
Κ.	Are all of the facts cited above adequately documented in the DTSC files? Yes X No

		If no, identify	areas	where	documentation is lacking	
10.	EPA	Involvement in the	Remed	lial Ac	ction:	
	Α.	Was the EPA invo	lved i	n the	site cleanup? Yes X No	
	В.	If yes, did EPA o			all remedial actions?	
	C	EPA comments US dated October 6,	SEPA p	rovide	ed comments in a letter	
			., San	Franc	up: Richard T. Russell, P.E. (Name, Title) cisco, CA. 94105, (415)744-	
11	Othe	r Regulatory Agenc	y Invo	lvemen	nt in the Cleanup Action:	
	Agen	icy: Ad	ctivit	y:		
	X	RWQCB	BRAC	Cleanu	ıp Team (BCT) member	
		ARB				
		CHP				
		Caltrans				
		Other				
	Name	Name of contact persons and agency:				
	Joh	John Broderick, Santa Ana Regional Water Quality Control				
	Во	ard (RWQCB).				
12.	Post-Closure Activities:					
	Α.				activities at this site? ance) Yes NoX_	
		If yes, describe				

	В.	Have post-closure plans been prepthe Department? Yes No	pared and approved by					
	С.	What is the estimated duration of (including operations and mainter years.						
	D.	Are deed restrictions proposed of Yes NoX	in place?					
	If "yes" have deed restrictions been recorded with the County recorder? Yes No Date If "no", who is responsible for assuring that the deed restrictions are recorded?							
		Who is the Division contact? Name/	Phone Number					
	E.	Has cost recovery been initiated	YesNo_X					
		If yes, amount received \$costs.	_;% of DTSC					
	F.	Were local planning agencies notication? Yes X No If yes, the agency: March Joint Powers Authority, ATAlbright, P.O. Box: 7480, Moreno	e name and address of CTN: Mr. Stephen					
13.	Expe	nditure of Funds and Source:						
	(Inf	ormation to be supplied by Toxic A	Accounting Unit.)					
	Fund	ing Source and amount expended:						
		HWCA \$	HSA \$					
		HSCF \$	RCRA \$					
		RP \$	Others \$					
	X	Federal Cooperative Agreement \$	800,000.00					
14.		ification Statement: Based upon thurrently and actually known to the						
	The Department has determined that all appropriate response actions have been completed, that all acceptable engineering practices were implemented and that no further removal/remedial action is necessary.							

	The Department has determined, based upon a remedial investigation or site characterization that the site poses no significant threat to public health, welfare or the environment and therefore implementation of removal/remedial measures is not necessary.
	The Department has determined that all appropriate removal/remedial actions have been completed and that all acceptable engineering practices were implemented; however, the site requires ongoing operation and
	maintenance (O&M) and monitoring efforts. The site will be deleted from the "active" site list following (1) a trial operation and maintenance period and (2) execution of a formal written settlement between the Department and the responsible parties, if appropriate. However, the site will be placed on the Department's list of sites undergoing O&M to ensure proper monitoring of long-term clean-up efforts.
Addi+	ional Commonts:

16. Certification of Remedial Action:

I hereby certify that the foregoing information is true and correct to the best of my knowledge.

16. Certification of Remedial Action:

Ι	hereby	certify	that the	foregoing	information	is true	and
	rrect t			knowledge	11		
		P 701 200	ON				
	1169	JAD B. YE					
	1191	Mr.	SI 211				
	110	~		$\stackrel{\sim}{\sim}$			
		No. C05379	98 3	> M		/ /	
	6(元 /	- 6/30/	as m	hand lon	n. A 10	13/90	-
1.	1+1	EXP. =7007	79 / 2/1/	nuce Bu	us 10		
	f/ But	ąd B. Yen	ut/Æ/E.	, /	7	Pate	
	NE ES) ect/Mar	rader.			,	
	Total Control of the	OF CALL	:01	_			

Base Closure Unit

John E. Scandura, Chief of Operations Southern California Office of Military Facilities

DEPARTMENT OF TOXIC SUBSTANCES CONTROL

Region 4 245 West Broadway, Suite 425 Long Beach, CA 90802-4444

(310) 590-4856

October 20, 19195

Lt. Jim Bray
Naval Facilities Engineering Service Center
Code ESC 112
560 Center Drive
Port Hueneme, California 93043-4328

Dear Lt. Bray:

TECHNICAL MEMORANDUM FOR THE REMOVAL STUDY CONDUCTED AT SITES 1, 2, AND 3, NAVAL CIVIL ENGINEERING LABORATORY (NCEL) PORT HUENEME

The California Environmental Protection Agency (Cal/EPA) and the Department of Health Services (DHS) has completed review of the above-mentioned document.

The DHS comments attached address Site 3, the former Radioisotope laboratory for NCEL (Building 597) only and does not address Sites 1 and 2.

Cal/EPA hereby concurs with the Radiological Affairs Support Office (RASO) conclusion of "no further action" required at Site 3 of NCEL.

John E. Scandara, Chief Office of Military Facilities Southern California Operations

Enclosure

cc: Mr. Todd Margrave
Southwest Division
Naval Engineering Facilities Command
1220 Pacific Highway
San Diego, California 92132-5181

Mr. Jim Ross
California Regional Water Quality
Control Board
Los Angeles Region
101 Centre Plaza Drive
Monterey Park, California 91754-2156



DEPARTMENT OF TOXIC SUBSTANCES CONTROL

Region 4 245 West Broadway, Suite 425 Long Beach, CA 90802-4444 (310) 590-4868



October 6, 1995

Lt. Jim Bray
Naval Facilities Engineering Service Center
Code ESC 112
560 Center Drive
Port Hueneme, California 93043-4328

Dear Lt. Bray:

ACTION MEMORANDUM FOR REMOVAL ACTION AT NAVAL FACILITIES ENGINEERING SERVICE CENTER, INSTALLATION RESTORATION SITE 1 AND SITE 2, PORT HUENEME, CALIFORNIA

The California Environmental Protection Agency (Cal/EPA) has completed review of the above mentioned document dated September 29, 1995. The draft document was published in a local newspaper and public comment period closed September 27, 1995. No comments were received to respond to.

Cal/EPA hereby concurs with the final Action Memorandum as submitted by the Navy.

Sincerel

John E. Scandura, Chief Office of Military Facilities Southern California Operations

cc: Mr. Todd Margrave
Southwest Division
Naval Engineering Facilities Command
Code 1821 TM
1220 Pacific Highway
San Diego, California 92132

Mr. Jim Ross
California Regional Water Quality
Control Board
Los Angeles Region
101 Centre Park Drive
Monterey Park, California 91754

